

| Product | Version | Theme | Environment | Date | Department | Person | Language |
|---------|--------------------|--------|-----------------------|------------|------------|----------------------|----------|
| XELEC | 7.12/B, V 7.20A | XVALID | COMPATIBLE WINDOWS | 03/08/2012 | Quality | Technical Support | EN |

Object:

RESET THE SIGNATURE OF A XElec FILE

Solution:

1. You must edit the file "permission.cfg" located under the directory of your "user" situated in the installation directory of XElec.
Example, My user is "fbe" so the directory is situated under "Disk name":\Xeiec\Users\fbe\xaccueil
2. Open the file "permission.cfg" and modify the variable of the resetting of the signature by placing a 1: (Attention to open the directory of your directory of your proper profile Windows !!!)

```

permission.cfg - Bloc-notes
Fichier Edition Format Affichage ?

APPLICATION_XSEA          2
Editeur_fichier_de_selection  1
Editeur_fichier_de_valeur    1

APPLICATION_XVALID        8
Effacement_de_la_derniere_signature  1
Fichiers_de_validation      1
Changer_le_format_des_listes  1
Mise a zero de la signature  1
Deblocage_de_la_numerotation  1
Genera_et_gestion_des_charts  0
Generation_de_FNR           1
Listes_tenants-aboutissants  0

APPLICATION_XATS          2
Editeur_fichier_de_selection  1

```

2. Save your file.

3. Open Xelec, then start Xvalid, you can after that reset your signatures.

| |
|--|
| <p>DOC. DE TRAVAIL</p> <p>DISQUE: xelec</p> <p>AFFAIRE: Peintamelec</p> <p>PROJET: peintamelec</p> <p>DOCUMENT: 03440-00100-UCC--</p> <p>ENV. ASSOCIE: michelin</p> |
| <p>COMMANDES</p> <p>Effacement dernière signature</p> <p>Fichiers de validation</p> <p>Changer le format des listes</p> <p>Mise à zéro de la signature</p> <p>Déblocage de la numérotation</p> <p>Génération de fichier FNR</p> |