| Product            | Version | Theme | Environment | Date | Department | Person   | Language |
|--------------------|---------|-------|-------------|------|------------|----------|----------|
| SEE Electrical PLM | V4Rx    |       | Windows     |      | R & D      | Designer | EN       |

## Subject:

## License installation for EED Mass Processing on PLM Hub computer

## Decription:

"Wire/Wire group calculation" and "Assign End-Fitting part Numbers" processes fail under Topology module without clear explanation or messages reporting any business processing.

## Our proposed solution:

After installation of SEE Electrical PLM - Application Server, an x64 version of SEE EED has been installed. This version is used by SEE Electrical PLM - Hub to run the above processes.

You have to verify that your SeeStencil.xml file (license file) is present and correct in the installation directory, usually: C:\Program Files\IGE+XAO\SEE Electrical Equipment Definition VxRy\See\_Soft\Exe